

' 1 R

A 89 1 0 0 24 29-38, 38, 20 ~28 -26 0 0 0 FIG. 1








FIG. 8(a)







FIG. 8(b)











FIG. 14






FIG. 15(c)





FIG. 15(d) TRANSMISSION ERROR TRANSMISSION FAILED.



LEGEND ON THE PUMP NOT BEING LIT. TO PLACE THE PUMP IN THE COMPUTER CONTROL MODE, PRESS THE

MODE AS INDICATED BY THE COMPUTER CONTROL

OPTIONS KEY LOCATED ON THE PUMP FRONT PANEL

- THE PUMP MODULE IS NOT CONNECTED TO THE PUMP.

AUTHORIZED PERSONNEL FOR COMPUTER CONTROL

THE PUMP HAS NOT BEEN CONFIGURED BY

DONE TO SCREEN 105

FIG. 15(e)

DEC 15, 00 07:11 028

TRANSMIT TO PUMP TRANSMISSION NOT SUCCESSFUL

THE TRANSMISSION FROM THE PDA TO THE PUMP WAS NOT SUCCESSFUL.

THE MEDICATION PROGRAMMING PARAMETERS (eg. FLOW RATE, VOLUME TO BE DELIVERED, ETC.) WERE FOUND TO BE OUTSIDE ACCEPTABLE PROGRAMMING LIMITS FOR THE PUMP.

TO CORRECT THIS SITUATION, THE OFFENDING PARAMETER MUST BE ADJUSTED.




FIG. 15(f)




FIG. 15(g)






FIG. 15(h)



DONE

FIG. 15(i)



DONE

TO SCREEN 031

FIG. 15(j)




FIG. 15(k)

DEC 15, 00 07:11

030

TRANSMIT TO PUMP MODULE EARLY MEDICATION DELIVERY



THIS MEDICATION IS BEING DELIVERED TO THE PATIENT EARLY. THE PRESENT TIME IS AT LEAST ONE HOUR EARLIER THAN THE EXPECTED DELIVERY TIME.

IF YOU WOULD LIKE TO STILL DELIVER THIS MEDICATION TO THE PATIENT, PRESS THE CONTINUE BUTTON ON THE EARLY MEDICATION DELIVERY SCREEN (SCREEN 29).

IF YOU WOULD PREFER NOT TO DELIVER THIS MEDICATION TO THE PATIENT, PRESS THE CANCEL BUTTON.

DONE

DEC 15, 00 07:11	014
PATIENT ID: B0031900318	
PATIENT NAME: HITCHCOCK, JAMES R WEIGHT: 75Kg	WEIGHT: 75Kg
PATIENT LOCATION: ROOM 211 BED 2	
MEDICAL RECORD #: 863291	
DATE OF BIRTH: 0711/79 AG	AGE: 21 YEARS
DATE OF ADMISSION: 11/15/00 SEX:	×.
PRIMARY PHYSICIAN: DR. BUI	

FIG. 17

DEC 15, 00 07:11 015	10
PATIENT INFORMATION HELP	
TO SCAN THE PATIENT'S ID BRACELET:	
1. AIM THE BAR CODE SCANNER HEAD AT THE BAR CODE LOCATED ON THE PATIENT ID BRACELET.	
2. POSITION THE BAR CODE SCANNER WINDOW FROM ONE TO FIVE INCHES FROM THE BAR CODE.	
3. PRESS THE LEFT OR RIGHT BUTTON TO INITIATE THE PATIENT ID BRACELET SCAN.	
CANCEL	

TO SCREEN 002

CONTINUE

TO LAST ACTIVE SCREEN

DEC 15, 00 07:11 016
PATIENT ID: B0031900318 PATIENT NAME: HITCHCOCK, JAMES R WEIGHT: 75 Kg PATIENT LOCATION: ROOM 211 BED 2
ORDER #: 3265894 BAG ID: 001215-01 MEDICATION: D5W WITH 20 mEg KCI VOLUME: 1000 mL RATE: 125 mL/hr
PREPARED BY: J. FROBEL 12/14/00 4:29 PM SOLUTION EXPIRES AT 7:00 PM ON 12/15/00 DELIVERY TIME TO PATIENT: 12/15/00 AT 07:00 ADMINISTRATION ROUTE: PERIPHERAL

FIG. 19

IV CONTAINER INFORMATION HELP TO SCAN THE IV CONTAINER BAR CODE: CODE LOCATED ON THE IV CONTAINER LABEL CODE LOCATED ON THE IV CONTAINER LABEL POSITION THE BAR CODE SCANNER WINDOW FROM ONE TO FIVE INCHES FROM THE BAR CODE THE IV CONTAINER LABEL SCAN THE IV CONTAINER LABEL SCAN CANCEL
SC SE RT ST RT


AT: 12/15/00 07:11

HUNG BY: J. SMITH

CONTINUE

TO SCREEN 005

TO LAST ACTIVE SCREEN



DEC 15, 00 07:11	020	
IV CONTAINER LABEL SCAN SCAN NOT SUCCESSFUL		

THE IV CONTAINER LABEL SCAN WAS NOT SUCCESSFUL THE POTENTIAL CAUSES OF THIS ERROR ARE:

- THE BAR CODE SCANNER WAS NOT AIMED AT THE BAR CODE ON THE IV CONTAINER LABEL.
 - THE BAR CODE SCANNER WAS TOO NEAR THE IV
- THE BAR CODE SCANNER WAS TOO FAR FROM THE IV CONTAINER LABEL.
- THE IV CONTAINER LABEL WAS DIRTY.
- THE BAR CODE SCANNER HEAD WAS DIRTY.
- THE IV CONTAINER LABEL BAR CODE IS ILLEGIBLE.

CONTINUE

TO SCREEN 007

FIG. 23

021	
DEC 15, 00 07:11	

TRANSMIT TO PUMP PATIENT ID BRACELET NFORMATION MISSING



IN ORDER TO TRANSMIT INFORMATION TO THE PUMP BOTH THE PATIENT ID BRACELET AND IV CONTAINER INFORMATION MUST BE PRESENT AND CORRESPOND TO EACH OTHER.

THE PATIENT ID BRACELET INFORMATION WAS FOUND TO BE MISSING.

TO CORRECT THIS SITUATION, SCAN THE PATIENT BRACELET BAR CODE INFORMATION INTO THE PALM PILOT

CONTINUE

DEC 15, 00 07:11 022
TRANSMIT TO PUMP
IV CONTAINER INFORMATION MISSING
IN ORDER TO TRANSMIT INFORMATION TO THE PUMP BOTH THE PATIENT ID BRACELET AND IV CONTAINER
INFORMATION MUST BE PRESENT AND CORRESPOND
TO EACH OTHER.

THE IV CONTAINER INFORMATION WAS FOUND TO BE MISSING. TO CORRECT THIS SITUATION, SCAN THE IV CONTAINER LABEL BAR CODE INFORMATION INTO THE PALM

CONTINUE

TO SCREEN

FIG. 25

DEC 15, 00 07:11	023
TRANSMIT TO PUMP	
PATIENT ID BRACELET DOES NOT MATCH IV CONTAINER INFORMATION	



INFORMATION MUST BE PRESENT AND CORRESPOND IN ORDER TO TRANSMIT INFORMATION TO THE PUMP BOTH THE PATIENT ID BRACELET AND IV CONTAINER TO EACH OTHER.

TO NOT MATCH THE IV CONTAINER LABEL INFORMATION. TO CORRECT THIS SITUATION, SCAN THE APPROPRIATE THE PATIENT ID BRACELET INFORMATION WAS FOUND

BAR CODE INFORMATION INTO THE PALM PILOT.

CONTINUE

	024
00	
DEC 15, 00	07:11
۵	

TRANSMIT TO PUMP



TO TRANSMIT INFORMATION TO THE PUMP:

- AIM THE IR WINDOW LOCATED ON THE BOTTOM RIGHT OF THE PALM PILOT AT THE IR WINDOW LOCATED ON THE TOP LEFT OF THE PUMP.
- POSITION THE PALM PILOT IR WINDOW APPROXIMATELY SIX INCHES TO THREE FEET FROM THE PUMP.
- PRESS THE TRANSMIT BUTTON ON THE PALM PILOT.

TO SCREEN 011

FIG. 27

1		
	8	
1	DEC 15, 00	07:11
)		0
'		
		•

025

TRANSMIT TO PUMP
TRANSMISSION NOT SUCCESSFUL




THE TRANSMISSION FROM THE PALM PILOT TO THE PUMP WAS NOT SUCCESSFUL. THE POTENTIAL CAUSES OF THIS ERROR ARE:


- THE PALM PILOT IR WINDOW WAS NOT AIMED AT THE PUMP IR WINDOW.
- THE PALM PILOT IR WINDOW WAS TOO NEAR THE PUMP IR WINDOW.
- THE PALM PILOT IR WINDOW WAS TOO FAR FROM THE PUMP IR WINDOW.
- THE PALM PILOT IR WINDOW WAS DIRTY
 - THE PUMP IR WINDOW WAS DIRTY.


CONTINUE

FIG. 28



TO SCREEN 008, 009, 010 or 011 036 WEIGHT: 75 Kg TO SCREEN FIG. 29(b) SOLUTION EXPIRES: 7:00 PM ON 12/15/00 905 IV CONTAINER SCAN ADMINISTRATION ROUTE: PERIPHERAL DEC 15, 00 07:11 LOCATION: ROOM 211 BED 2 NAME: HITCHCOCK, JAMES R PREPARED BY: J. FROBEL PATIENT ID: B0031900318 TO BE DELIVERED WITH: TAP THE APPROPRIATE **ICON TO CONTINUE** PAGE 1 **10 SCREEN** 035 TO SCREEN 008, 009, 010 or 011 035 WEIGHT: 75 Kg UKUEK #: 3265894 BAG ID: 001215-01 SEC MEDICATION: ZYTHROMAX DELIVERY TO PATIENT: 12/15/00 AT 7:00 FIG. 29(a) **TO SCREEN** IV CONTAINER SCAN 50 mL/hr 905 DEC 15, 00 07:11 LOCATION: ROOM 211 BED 2 NAME: HITCHCOCK, JAMES R VOLUIME: 50 mL RATE: PATIENT ID: B0031900318 TAP THE APPROPRIATE **ICON TO CONTINUE** PAGE 2 **TO SCREEN** 036









FIG. 34(a)



PRESS THE APPROPRIATE BUTTON

TO INITIATE A CHANGE.

VERBAL RATE CHANGE

FIG. 33

SEC MED MED

CANCEL

. 된 일 TO SCREEN 044


PREVIOUS


10

TO SCREEN

043

SCREEN








FIG. 36(b)





FIG. 36(c)



r	Y	<u>、</u> つ
C	F)
Ĺ		

F. 38

S S

	MULTIPLE CONTAINERS	SELECT THE PRIMARY AND SECONDAR MEDICATIONS		MEDICATION :	PRIMARY SECONDAR	MEDICATION :	O PRIMARY ® SECONDAR		CANCEL OK	
X 2	MULTIPLE CONTAINERS	SELECT THE MEDICATION YOU WANT TO USE	MEDICATION:	KEEP THIS MEDICATION	MEDICATION:	✓ KEEP THIS MEDICATION	MEDICATION :	✓ KEEP THIS MEDICATION	CANCEL OK	

7

?×

TRANSMIT TO PUMP MODULE



ALLERGY ALERT

MEDICATION CONTAINS AN ALLERGY DISCREPANCY FOR THIS PATIENT.

TRANSMISSION TO PUMP MODULE PROHIBITED.

CANCEL